

TSI/GRAYWOLF

- 1. The end user sends the completed form "APHC IH Maintenance Request User" to (email: usarmy.apg.medcom-phc.mbx.ohs-equipment-maintenance@mail.mil):
- One form per each piece of equipment/serial number with exception of the velometer which then all probes need to be listed on the form (probes can be listed in the description box).
 - Make sure to select if calibration only, repair only, or calibration and repair are needed.
- 2. A return e-mail will be provided with:
 - a ticket number for steps below and for reference if any questions arise
- RMA (return merchandise authorization), which is the unique identifier from the contractor for each piece of equipment
 - the address of the calibration vendor
 - Fed Ex account log in information
- 3. The end user sends the equipment to the calibration vendor and sends an e-mail to: usarmy.apg.medcom-phc.mbx.ohs-equipment-maintenance@mail.mil with the ticket number, date sent and FEDEX tracking information.
- 4. The contractor has 10 working days from receipt of equipment to complete the calibration and send the equipment back to the end user.
- 5. As soon as the equipment is received by the end user, send a confirmation e-mail to: usarmy.apg.medcom-phc.mbx.ohs-equipment-maintenance@mail.mil and include the ticket number.

NOTE: End Users WILL NOT contact the calibration vendor; doing so will result in an Anti-Deficiency Act Violation. We monitor the FedEx account and will report unauthorized uses.