



How to Borrow IH Equipment:

Step One: Coordinate with your Regional Health Command at the following contact phone numbers, if they cannot support you, then contact the APHC Equipment Laboratory via the link.

- RHC-Atlantic: 301.677.6426
- RHC-Central: 210.221.3284
- RHC-Europe: 314.486.8237
- RHC-Pacific: 315.263.8497
- APHC: usarmy.apg.medcom-aphc.mbx.ihequipmentrequest@mail.mil

Step Two: Send an e-mail request as directed by the contact at the RHC or APHC with the following information.

- Name of requestor
- FedEx Shipping Address
- Phone Number
- E-mail
- IH Equipment requested and quantity (e.g. MultiRAE IR Multi Gas Analyzer, Jerome Mercury Vapor Analyzer, 5 Gilian Air Sampling Pumps)
- Reason you need to borrow the IH equipment (e.g. Indoor Air Quality Surveys; Aggressive Sampling Plan for Indoor Firing Ranges)
- Date IH equipment required
- Date IH equipment will be returned (30 calendar days maximum)